

A technical line drawing showing a mechanical assembly. A large, L-shaped base plate with several circular holes is shown. A curved component, possibly a spring or a flexible arm, is being inserted into a slot in the base plate. A dashed line indicates the path of the component. A small rectangular component with two circular features is attached to the end of the curved component. An arrow points to the curved component, and another arrow points to the small rectangular component.

[illegible]